2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

2003-08 TRANSMISSION

Transfer Box - 9pa_Cayenne

TRANSFER BOX

INTRODUCTION

Transfer box (VG)

Diagnosis software number: VG 0101

Cayenne model year 2003

General instructions/safety instructions

CAUTION: Danger of damage due to improper handling of batteries and control module plug connections!

- Never disconnect battery with engine running.
- Never start engine if battery terminal clamps are not connected securely.
- Never pull off or push on plug connections for the control modules or other electronic components when the ignition is switched on.
- Always disconnect the negative terminal of the battery and pull off all plug connections to the 'vehicle electrical system control module' when carrying out welding work on the vehicle.

WARNING: Danger of injury and damage due to unusual vehicle handling when plugs or components are disconnected!

- Never disconnect plugs when the vehicle is in motion or drive the vehicle with plugs disconnected.
- Drive only with all parts fully installed and connected.

Communication between transfer box control module and Porsche System Tester II No. 9588

NOTE: The following conditions must be met in order to establish communication between the transfer box control module and the Porsche System Tester II No. 9588:

- Porsche System Tester II No. 9588 connected to data link connector
- The battery voltage must be greater than 6.5 V

General information on the fault memory

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

The fault memory of the control module can save up to (X) different faults simultaneously. If all (X) fault memories are full, the new fault overwrites the oldest fault. The fault memory content of the 'transfer box control module' is maintained even in removed state.

Fault code setting conditions

Fault codes can be set in various circumstances, e.g.:

- battery disconnected
- plug connections disconnected
- faulty coding
- power failure
- etc.

In these circumstances, no fault is present in the system and the fault memory must be erased.

Troubleshooting procedure

Troubleshooting can only be performed when the fault is present. In other words, specific troubleshooting can only be performed in accordance with instructions (given under Diagnosis/troubleshooting for each fault code) if the entry has the status 'present' in the fault memory.

If the fault is currently 'not present', please check the following:

- Diagnostic conditions are met
- All plug connections and ground points of the affected current path are OK
- View the fault frequency counter in the Porsche System Tester II No. 9588 using the fault memory Info key [F8] under 'Extended fault memory' and try to reach conclusions about eliminating any loose contacts in the system.

Diagnostic conditions

IMPORTANT: Always connect a suitable battery charging device to the vehicle electrical system battery before starting diagnosis. All unnecessary loads must also be switched off.

NOTE: The fault can only be identified if the requirements listed under 'Diagnostic conditions' are met. For this reason, the specified procedure must be observed after a fault is repaired:

- 1. Erase fault memory
- 2. Satisfy the requirements listed under 'Diagnostic conditions'.
- 3. Read out fault memory again.

Possible causes of fault

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

NOTE: The 'possible causes of fault' that are responsible for the fault are listed here. Please note that in certain circumstances further faults can be stored in the fault memory after troubleshooting (e.g. if plugs are disconnected). After carrying out repairs, read out the fault memory of all control modules and erase any faults.

Diagnosis/troubleshooting

NOTE: The fault memory Info key [F8]on the Porsche System Tester II No. 9588 can be used to access the 'extended fault memory'. The following information can be displayed:

Fault type

The following fault types are possible:

- no display
- upper limit value exceeded
- lower limit value not reached
- mechanical fault
- no signal/communication
- no or incorrect basic setting/adaptation
- short circuit to B+
- short circuit to ground
- implausible signal
- open circuit/short circuit to ground
- open circuit/short circuit to B+
- open circuit
- electrical fault in electric circuit
- please read out fault memory
- faulty
- cannot be checked now

Fault status

The following status types are possible:

- present
- not present

This information should be saved using the Save key [F4] and printed out.

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

NOTE: Visual inspection: During troubleshooting, please check first that the affected pins on the control module plug connection are neither damaged nor corroded. The wires and plugs of the affected components must also be checked for external damage and correct contacts. Repair damaged or corroded pins if possible, otherwise replace affected pins. Repair or replace damaged wires.

NOTE: Battery voltage: A battery voltage of between 11.4 and 14.5 V is required for troubleshooting. This must be checked and provided if necessary. Voltages to components or fuses (input side) must be guaranteed on the vehicle electrical system.

Freeze frame (frozen fault boundary conditions)

Freeze frame data is standardised and records operating conditions in the event of a fault. Freeze frames have different priorities, which can be important when output to a Scan Tool. These can be viewed in the "extended fault memory" of the Porsche System Tester II No. 9588.

Furthermore, various operating conditions can be stored for each fault. These can provide reference points for determining the cause of a fault in the case of difficult diagnoses. These can be viewed in the "extended fault memory" of the Porsche System Tester II No. 9588.

Fault deletion counter

An individual deletion counter runs for every fault detected. It determines the storage duration of the related fault.

When a fault is first detected, the deletion counter is set to 80, for example (suspected fault).

If an unshedded fault is detected as having been remedied, the deletion counter is set to 10, for example (fault did not occur often enough to be confirmed).

Whenever a shedded fault is detected, the deletion counter is set to 40, for example. This value is retained until the fault is detected as having been remedied.

The deletion counter is decremented by 1 after every warm-up cycle if the fault in question is an unshedded fault or is detected as having been remedied (faults that are confirmed, but are not detected as having been remedied are not decremented in the deletion counter). If the deletion counter reaches the value 0, the fault is deleted from the memory.

Fault frequency counter

This counter shows how often a fault has recurred following its first occurrence. If the frequency value is 1, the fault has only occurred once. It can now be either "present" or "not present". The fault frequency counter is incremented whenever this fault recurs (the fault healing counter was decremented in the meantime, i.e. a check was performed and found to be OK). A higher value in the fault frequency counter can therefore indicate a loose contact.

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

TOOLS - TRANSFER BOX


WARNING: Danger of personal injury while driving with special tools

• Never hang the Porsche System Tester II No. 9588 over the steering wheel!

NOTE:

- Before starting the diagnosis a suitable charging device must be connected to maintain battery capacity.
 - Plug contacts are optimally designed to suit the plug system. Operations on pins can cause contact problems. Always use suitable measurement tools for adapter plugs and test cables.

BATTERY CHARGING DEVICE



<u>Fig. 1: Identifying Battery Charging Device</u> Courtesy of PORSCHE OF NORTH AMERICA, INC.

PORSCHE SYSTEM TESTER II NO. 9588



Fig. 2: Identifying Porsche System Tester (9588) Courtesy of PORSCHE OF NORTH AMERICA, INC.

COMMERCIALLY AVAILABLE DIGITAL MULTIMETER

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne



Fig. 3: Identifying Commercially Available Digital Multimeter Courtesy of PORSCHE OF NORTH AMERICA, INC.

MEASUREMENT TOOL SET NO. 9684




9684 000 721 968 40

<u>Fig. 4: Identifying Measurement Tool Set (9684)</u> Courtesy of PORSCHE OF NORTH AMERICA, INC.

COMPONENT ARRANGEMENT - TRANSFER BOX

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne



a - CAN drive (CAN-C)

1 - DME control module

Located in right radiator tank, above hydraulic unit with PSM control unit

2 - Fuse carrier at right of dashboard

Integrated into right side of dashboard

3 - Level control unit

Located between rear right wheel housing and closing panel

4 - Transverse lock control unit

Located between rear left wheel housing and closing panel

5 - Vehicle electrical system control unit (connected to CAN comfort)

Located on right side of steering column (footwell) near KESSY control unit

6 - Transfer box with components Servo motor

7 - Instrument cluster (includes the gateway)

Integrated into dashboard

8 - Tiptronic control module

Located on vehicle floor under passenger's seat (LHD) (front right)

9 - Transfer box control unit

Located on vehicle floor under passenger's seat (LHD) (front right)

10 - Selector switch (running gear control module)

Located near selector lever module (Tiptronic)

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Fig. 5: Identifying Transfer Box Component Arrangement Courtesy of PORSCHE OF NORTH AMERICA, INC.

Component arrangement 'Item 6' Transfer box with components

- 1 Transfer box servo motor
- A Servo motor plug connection (power and ground supply for brake and motor)
- **B** Sensor plug connection




Fig. 6: Identifying Transfer Box Servo Motor And Servo Motor Plug Connection Courtesy of PORSCHE OF NORTH AMERICA, INC.

Component arrangement 'Item 10' Selector switch (running gear control module)

- 1 Selector switch housing
- 2 Selector switch housing lower part
- 3 Symbols 'Level control LED'
- 4 Slider 'Manual set level'
- 5 Switch 'PASM running gear tuning'
- 6 Slider 'Manual set longitudinal lock/transverse lock/gear reduction'
- 7 Symbols 'Longitudinal lock/transverse lock/gear reduction LED'

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne




Fig. 7: Identifying Selector Switch Component Arrangement Courtesy of PORSCHE OF NORTH AMERICA, INC.

CONNECTOR ASSIGNMENT - TRANSFER BOX CONTROL UNIT

PLUG '47-PIN'




Fig. 8: Identifying Transfer Box Control Unit Plug Connector 47-Pins Courtesy of PORSCHE OF NORTH AMERICA, INC.

CONNECTOR TERMINALS REFERENCE CHART

Pin	Designation	Pin	Designation
1	Potentiometer '1' (sensor 1) 5 V	2	Ground, potentiometer '1' (sensor 1)
3	Not assigned	4	Gear reduction LED
5	Not assigned	6	Not assigned
7	PWM switch (Pulse Width Modulation)	8	Switch contact for transverse lock, left
9	Neutral switch MT (manual transmission only)	10	Not assigned
11	CAN drive (low)	12	Input signal, potentiometer '1' (sensor 1)

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

13	Not assigned	14	Not assigned
15	Servo motor (A)	16	Servo motor (B)
17	Terminal 30 (electronics)	18	Potentiometer '2' (sensor 2) 5 V
19	Not assigned	20	LED longitudinal lock
21	Voltage supply to brake for servo motor (A)	22	Not assigned
23	K-line (diagnosis)	24	Not assigned
25	MOST switch	26	Parking brake
27	Not assigned	28	Not assigned
29	Voltage supply (5V) for servo motor temperature sensor	30	Not assigned
31	Input signal, potentiometer '2' (sensor 2)	32	Not assigned
33	Ground output, potentiometer '2' (sensor 2)	34	Not assigned
35	LED transverse lock	36	Ground supply to brake for servo motor (B)
37	Not assigned	38	Not assigned
39	Not assigned	40	Switch contact for transverse lock, right
41	Terminal 15	42	CAN drive (high)
43	Longitudinal lock oil temperature	44	Ground, servo motor temperature sensor
45	Not assigned	46	Terminal 30
47	Ground		

Gear selection switch connector assignment (running gear control module), '16-pin'

A - Plug connection for 'gear selection switch (running gear control module)' (at underside of housing)




Fig. 9: Identifying Gear Selection Switch Connector 16-Pins Courtesy of PORSCHE OF NORTH AMERICA, INC.

CONNECTOR TERMINALS REFERENCE CHART

Pin Designation		Designation		
Not assigned	2	Not assigned		
Button for transverse lock switch 'neutral'	4	PWM locks		
Not assigned	6	LED transverse lock		
	Designation Not assigned Button for transverse lock switch 'neutral'	DesignationPinNot assigned2Button for transverse lock switch 'neutral'4		

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

7	K-line (diagnosis)	8	Terminal 31, ground pin 'MB 22'
9	Not assigned	10	Not assigned
11	Output from transverse lock button 'negative'	12	Output from transverse lock button 'positive'
13	Gear reduction LED	14	LED longitudinal lock
15	Terminal 58d, orientation light	16	Terminal 15

CONTROL MODULE FUNCTION (CODING/PROGRAMMING)

INTEGRATED FUNCTIONS

The transfer box control module includes the functions listed below:

- Computer identification
- Computer configuration with ignition ON
- Checking the fault memory for fault entries, even in diagnostic mode
- Deleting the fault memory
- Reading measured values from switches and sensors

Supported functions:

- Diagnosis software number
- Drive link test with active fault checking

Basic setting:

- Adaptation/Resetting adaptation values
- Read memory
- Write memory
- Update programme
- Flash programme (end of volume)
- Protected against unauthorised access

COMMISSIONING

When the ignition 'terminal 15' is switched on, an internal function test (initialisation phase) is performed in the transfer box control module. When the internal function test is completed successfully, all functions integrated into the transfer box control module are released.

OPERATING MODE

The transfer box control module is in operating mode once the ignition is switched on and the internal function test is completed successfully. Within the defined limits for power supply and temperature, all incoming signals are processed by the integrated software and the appropriate monitoring and control processes are performed.

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

DATA TRANSFER

The transfer box control module sends and receives data/information via the following 'CAN data bus':

- CAN drive (C)
- Gateway (in instrument cluster)

DIAGNOSIS

Fault memory

Faults that occur during operation are stored in a non-volatile memory (e.g. EEPROM). The faults remain in the memory even if terminal 15 and terminal 30 are not live. The fault memory is designed in such a way that the occurring faults, data source, fault type and fault deletion counter can be saved. The transfer box control module sends messages and checks the CAN drive cyclically for messages from other control modules. If no messages are received for a certain time period, a fault is stored in the fault memory.

ADAPTATION

Work to be carried out after replacing a control module:

• Delete the adaptation values using the Porsche System Tester II No. 9588

CODING

NOTE: The transfer box control module does not have to be coded!

FAULT OVERVIEW - TRANSFER BOX CONTROL UNIT

Fault code	Fault text	Fault effects
<u>0532</u>	Power supply	• The functions available in the transfer box control unit cannot be enabled.
<u>0659</u>	Self-test	• The functions available in the transfer box control unit cannot be enabled.
<u>0778</u>	Steering-angle sensor	• -
1312	CAN drive	• -
<u>1314</u>	DME control unit	• -
<u>1315</u>	Tiptronic control unit	• -
<u>1316</u>	PSM control unit	• -
<u>1317</u>	Instrument cluster	• -

FAULT REFERENCE CHART

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

<u>1336</u>	CAN comfort OFF	• -
<u>2025</u>	Power supply	• -
2033	Potentiometer 2, transfer box	• -
<u>2038</u>	Power supply, sensors	• -
<u>2039</u>	Potentiometer, transfer box	• -
<u>2040</u>	Voltage supply to transfer box servo motor	• -
<u>2041</u>	Ground supply to transfer box servo motor	• -
<u>2042</u>	Activation of transfer box servo motor	• -
<u>2046</u>	Gear reduction LED (in control module)	• -
<u>2047</u>	Centre-differential lock LED (in control module)	• -
<u>2048</u>	Rear-differential lock LED (in control module)	• -
<u>2050</u>	Transfer box switching fault	• -
<u>2051</u>	Tiptronic control unit - incorrect software version	• -
<u>2052</u>	Control unit switched off due to excess temperature	• -
<u>2053</u>	Transfer box control unit	• -
2054	Rear-differential lock control unit	• -
<u>2057</u>	Power supply to brake servo motor (A)	• -
<u>2058</u>	Ground supply to brake servo motor (B)	• -
<u>2059</u>	Servo motor temperature sensor	• -
<u>2060</u>	Power supply to servo motor temperature sensor	• -
<u>2373</u>	Current sensor in control unit	• -
<u>2409</u>	Servo motor, brake	• -
<u>2411</u>	Centre-differential lock	• -
<u>16344</u>	Control unit faulty	• The functions available in the transfer box control unit cannot be enabled.
<u>16346</u>	Control unit faulty	• The functions available in the transfer box control unit cannot be enabled.
16347	Control unit faulty	• The functions available in the transfer box control

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		unit cannot be enabled.
<u>16353</u>	Control unit malfunction	• The functions available in the transfer box control unit cannot be enabled.
<u>16366</u>	Control unit malfunction	• The functions available in the transfer box control unit cannot be enabled.

FAULT CODE 0532

VOLTAGE SUPPLY

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible causes of fault

- 'Below lower limit', battery discharged or faulty
- 'Lower limit value not reached', fuse faulty
- 'Below lower limit', line short circuit to ground or open circuit
- 'Below lower limit', alternator faulty
- 'Below lower limit', transfer box control unit faulty
- 'Above upper limit', alternator faulty
- 'Above upper limit', transfer box control unit faulty

Affected pins

Transfer box control module plug:

- Pin 46 'terminal 30', from fuse carrier at right of dashboard 'fuse 57'
- Pin 47 'ground', from ground pin 'MB26'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pin' of the transfer box control unit plug connection and the 'pin' of the plug connections are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

damage the 'transfer box control unit' should be detected and remedied.

Before carrying out the work instruction, check fuse '57', voltage supply terminal 30 for the transfer box control unit, in the fuse carrier to the right of the dashboard and replace if necessary. After replacing the fuse, determine and remedy the cause of the fault in accordance with the work instruction below!

Display OK Work instruction If not OK Charge battery if necessary, replace if faulty. Wiring/regulator or diodes faulty. Repair wiring or generator. Check battery After carrying out repairs, erase the • Engine speed > 2,000voltage/current and fault memory and then read out the rpm. 11.4 to 14.5 V charge fault memory again while observing • Measure charge voltage/current on Go to Step 2 the diagnostic conditions. If no fault voltage/current of three-phase stored, then: generator. generator: --> End If fault reappears, then: Go to Step 2 Measurement '2a': • Ignition off Check fuse '57' in fuse carrier at • Pull plug off the 10.5 to 14.5 V right of dashboard (resistance transfer box control continue with measurement). Check voltage supply unit measurement line for short circuit to ground: '2b' Check terminal 30 • Measure voltage Go to Step 3 voltage supply and between 'pin 46' and 2 ground supply line to ground on transfer transfer box control box control unit plug. unit: Measurement '2b': • Measure voltage Check ground supply line for short 10.5 to 14.5 V between 'pin 47' and circuit to B+: Go to Step 3 battery terminal 30 on Go to Step 3 transfer box control unit plug. Measurement '3a': Short circuit to ground between transfer box control unit plug leads < 0.3 V Check power supply • Measure voltage 'pin 46 and fuse 57' in fuse carrier at line for short circuit between 'pin 46 and Measurement right of dashboard. Repair wiring to ground: battery positive' on '3b' and replace faulty fuse. transfer box control --> End unit plug. Short circuit to B+ between transfer

box control unit plug leads 'pin 47'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Check ground supply Measurement '3b':

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

	line for short circuit to B+:	• Measure voltage between 'pin 47' and ground on transfer box control unit plug.	< 0.3 V Go to Step 4	and ground pin MB26. Repair wiring and replace faulty fuse(s). > End
2	Check for open circuit of terminal 30 voltage supply line and ground supply line for ground pin MB26:	 Measure resistance on transfer box control unit plug between 'pin 46 and fuse 57' in fuse carrier at right of dashboard. Measure resistance between 'pin 47' and ground pin MB26 on transfer box control unit plug. 	< 0.5 ohms Go to Step 5	Open circuit in wire to fuse carrier at right of dashboard. Open circuit in wire to ground pin MB26. Repair wire(s). Also check fuse. > End
4	Check terminal 30 power supply at fuse:	• Measure voltage between fuse plug '57 and body ground' in fuse carrier at right of dashboard.	10.5 V to 14.5 V Go to Step 6	Short circuit/contact resistance/corroded or loose connections near or in fuse carrier. Repair if possible, otherwise replace fuse carrier at right of dashboard. > End
e	Replace transfer box c	control module	See note on rep > End	blacing control units!

FAULT CODE 0659

SELF-TEST

Diagnostic conditions

- Ignition on
- Internal control module function test not completed successfully

Possible causes of fault

• When the ignition is switched on, an internal function test is performed in the transfer box control module, but this was not completed successfully (implausible signal)

NOTE: The internal function test must be completed successfully before the functions in the transfer box control module can be released.

Affected pins

Transfer box control module plug:

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• -

• -

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: Before replacing the control module, the ground connections, power supply and plug connections on the control module must be checked. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the transfer box control module should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	1 0	If not OK
Delete the fault memory for the transfer box control module and restart the internal function test (ignition ON/test is performed automatically)	> End	Go to Step 2
2 Replace transfer box control module	> End	

FAULT CODE 0778

STEERING-ANGLE SENSOR

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible causes of fault

• No message from steering-angle sensor (no signal/communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

DIAGNOSIS TROUBLESHOOTING PROCEDURE

١	Vork instruction	Display OK	If not OK
	Read out fault memory for steering column switch (fault localisation)	For further fault localisation, please follow diagnosis/troubleshooting instructions for refer to the ANTI-LOCK BRAKE SYST troubleshooting description '0778 Steering from this. > End	the PSM control module, TEM (ABS) article . The
2	CHECKING INSTRUCTIONS/CAN DATA BUS .	> End	

FAULT CODE 1312

CAN DRIVE

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible cause of fault

Communication problem with all control modules via CAN drive.

- CAN drive is faulty
- No signal/communication

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	Display OK	If not OK
1 CHECKING INSTRUCTIONS/CAN DATA BUS .	> End	

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

FAULT CODE 1314

DME CONTROL MODULE

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

Communication problem with all control modules via CAN drive.

- To localise the fault, read out the fault memory for the 'DME control module' (Please read out fault memory)
- No message from DME control module on CAN drive (no signal/ communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

	Work instruction	Display OK	If not OK
	Read out fault memory for DME	To eliminate further faults, please follow the diagnosis/troubleshooting instructions for the DME control mo refer to the <u>OBD (II)</u> and <u>FUEL SYSTEM, ELECTRONIC</u> <u>INJECTION</u> articles . > End	
4	<u>CHECKING</u> 2 <u>INSTRUCTIONS/CAN DATA</u> <u>BUS</u> .	> End	

FAULT CODE 1315

TIPTRONIC CONTROL MODULE

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

- To localise the fault, read out the 'Tiptronic control module' fault memory (Please read out fault memory)
- No message from Tiptronic control module on CAN drive (no signal/communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	Display OK	If not OK
Read out fault memory for 1 Tiptronic control module (fault localisation)	control module (fault module, refer to the <u>TIPTRONIC</u> and <u>AUTOMATIC</u> .	
CHECKING 2 INSTRUCTIONS/CAN DATA BUS .	> End	

FAULT CODE 1316

PSM CONTROL MODULE

Diagnostic conditions

- Ignition on
- Internal control module function test
- Vehicle speed greater than 0 km/h

Possible cause of fault

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- To localise the fault, read out the fault memory for the 'PSM control module' (Please read out fault memory)
- No message from PSM control module on CAN drive (no signal/ communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

١	Vork instruction	Display OK	If not OK
1		To eliminate further faults, please follow diagnosis/troubleshooting instructions for module, refer to the <u>ANTI-LOCK BRA</u> article . > End	or the PSM control
	<u>CHECKING</u> INSTRUCTIONS/CAN DATA <u>BUS</u> .	> End	

FAULT CODE 1317

INSTRUMENT CLUSTER

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

- Signal from instrument cluster does not correspond to expected signal (please read out fault memory).
- Signal from instrument cluster does not appear on CAN drive (no signal/communication).

Affected pins

Transfer box control module plug:

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		Display OK	If not OK
11	Read out instrument cluster fault	For further troubleshooting, please follow the diagnosis instructions for the instrument cluster, refer to the INSTRUMENT CLUSTER article . > End	
2	<u>CHECKING</u> INSTRUCTIONS/CAN DATA <u>BUS</u> .	> End	

FAULT CODE 1336

CAN COMFORT OFF

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

- To localise the fault, read out the fault memory for the 'gateway (in instrument cluster)' (Please read out fault memory)
- No message from CAN comfort (the messages are transferred to the CAN drive via the 'gateway' interface in the instrument cluster) on CAN drive (no signal/communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

DIAGNOSIS TROUBLESHOOTING PROCEDURE

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

,	Work instruction	Display OK	If not OK
	Read out fault memory for gateway (in instrument cluster) (fault localisation)	For further fault localisation, please troubleshooting instructions for the cluster), refer to the INSTRUMEN > End	gateway (in instrument
	CHECKING INSTRUCTIONS/CAN DATA BUS .	> End	

FAULT CODE 16344

CONTROL MODULE FAULTY

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible cause of fault

• Transfer box control module faulty

Affected pins

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE:

- Before replacing the control module, the ground connections, power supply and plug connections on the control module must be checked.
- After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the transfer box control module should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	Display OK	If not OK
1 Replace transfer box control module	> End	

FAULT CODE 16346

CONTROL MODULE FAULTY

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Possible cause of fault

• Transfer box control module faulty

Affected pins

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE:

- Before replacing the control module, the ground connections, power supply and plug connections on the control module must be checked.
- After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the transfer box control module should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	Display OK	If not OK
1 Replace transfer box control module	> End	

FAULT CODE 16347

CONTROL MODULE FAULTY

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible cause of fault

• Transfer box control module faulty

Affected pins

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE:

- Before replacing the control module, the ground connections, power supply and plug connections on the control module must be checked.
- After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the transfer box control module should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		Display OK	If not OK
1	Replace transfer box control module	> End	

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

FAULT CODE 16353

CONTROL UNIT MALFUNCTION

This fault causes the power/voltage supply to the servo motor 'A/B', brakes 'A/B', sensors and CAN communication to switch off.

Diagnostic conditions

NOTE: The internal function test must be completed successfully before the functions stored in the transfer box control unit can be activated.

- Ignition on
- Internal transfer box control unit function test

Possible causes of fault

• 'Implausible signal': fault detected in computer during internal function test in transfer box control unit.

Affected pins

Transfer box control unit plug:

• Pin '-'

DIAGNOSIS/TROUBLESHOOTING

NOTE: Before replacing the control unit, the ground connections, power supply and plug connections on the control unit must be checked. After the test drive, read out the fault memory with the Porsche System Tester II No. 9588 again. Additional causes of faults that could damage the transfer box control unit should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

	Work instruction		If not OK
1	Delete the fault memory for the transfer box control unit and restart the internal function test (ignition ON/test is performed automatically)	> End	If fault is repeated, then: Go to Step 2
2	2 Replace transfer box control unit	> End	

FAULT CODE 16366

CONTROL UNIT MALFUNCTION

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

This fault causes the power/voltage supply to the servo motor 'A/B', brakes 'A/B', sensors and CAN communication to switch off.

Diagnostic conditions

NOTE: The internal function test must be completed successfully before the functions stored in the transfer box control unit can be activated.

- Ignition on
- Internal transfer box control unit function test

Possible causes of fault

• 'Implausible signal': fault detected in computer during internal function test in transfer box control unit.

Affected pins

Transfer box control unit plug:

• Pin '-'

DIAGNOSIS/TROUBLESHOOTING

NOTE: Before replacing the control unit, the ground connections, power supply and plug connections on the control unit must be checked. After the test drive, read out the fault memory with the Porsche System Tester II No. 9588 again. Additional causes of faults that could damage the transfer box control unit should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		If not OK
Delete the fault memory for the transfer box control unit and internal function test (ignition ON/test is performed automat	rootort the	If fault is repeated, then: Go to Step 2
2 Replace transfer box control unit	> End	

FAULT CODE 2025

POWER SUPPLY

Diagnostic conditions

- Ignition on
- Internal function test on transfer box control unit

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Possible causes of fault

- 'Short circuit to B+' between 'PWM (Pulse Width Modulation) switch' and 'selector switch (in running gear control module)'
- 'Short circuit to ground' between 'PWM (Pulse Width Modulation) switch' and 'selector switch (in running gear control module)'
- 'Open circuit' between 'PWM (Pulse Width Modulation) switch' and 'selector switch (in running gear control module)'

Affected pins

Transfer box control unit connector:

• Pin 7 'PWM (Pulse Width Modulation) switch' to 'pin 4' 'selector switch (in running gear control module)'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' on the transfer box control unit plug connection and the 'pins' on the plug connections on the 'selector switch (in running gear control module)' are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wiring.
- NOTE: Control unit replacement: before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked and found to be OK. After test-driving the vehicle, read out the fault memory again using the 9718 PIWIS tester. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		If not OK
Carry out the following checks on the wiring between 'pin 7' 'transfer box control unit' and 'pin 4' 'selector switch (in running gear control module)': Short circuit to B+ Short circuit to ground Open circuit	Go to Step 2	Repair or replace connector/wiring. > End
2 Replace selector switch (running gear control module)	> End	

FAULT CODE 2033

POTENTIOMETER 2, TRANSFER BOX

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

NOTE: This fault code relates to the signal of potentiometer '2' (sensor 2) which, together with potentiometer '1' (sensor 1) and the temperature sensor, is integrated as a unit in the servo motor.

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible causes of fault

- 'Short circuit to B+': signal line of potentiometer '2' (sensor 2) short circuit to B+(12 V)
- 'Short circuit to B+': transfer box control unit faulty
- 'Open circuit/short circuit to ground': signal line of potentiometer '2' (sensor 2) open circuit or short circuit to ground
- 'Short circuit to ground': potentiometer faulty
- 'Open circuit/short circuit to ground': transfer box control unit faulty

Affected pins

Transfer box control module plug:

• Pin 31 'input signal to potentiometer 2 (sensor 2)', from pin B8 of 'servo motor sensor plug'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'short circuit to B+'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

W	ork instruction	Display OK	If not OK
	Measurement '1a':		
	• Ignition off	< 0.3 V	Repair wiring

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		 Pull plug off the transfer box control unit Ignition on Measure voltage between 'pin 31' of transfer box control unit plug and ground. Measurement '1b': 	go to measurement '1b'	harness to servo motor. > End
1	Check short circuit to B+:	 Ignition off Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pin B8 and pins A1, A2, A3, A4' of servo motor plugs 'A and B'. Measure resistance between 'pin B8 and pin B4' of servo motor plug 'B'. 	infinity ohms go to measurement '1c'	Short circuit between servo motor leads. Go to Step 2
		 Measurement '1c': Measure resistance between 'pin 31' and pins '1, 15, 16, 18, 21, 36' of transfer box control unit plug. 	infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
2	Replace transf	er box servo motor	> End	·
3	Replace transf	er box control module	See note on repla > End	cing control units!

Troubleshooting fault type: 'Open circuit/short circuit to ground'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instructi	on	Display OK	If not OK
Check short 1 circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pin 31 and pins 2, 15, 16, 44, 47' of transfer box control unit plug. Measurement '1b': 	infinity ohms Go to Step 2	go to measurement '1b'
	 Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pin 31 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
	 Measurement '2a': Pull plug 'B' off servo motor Measure resistance between 'pin B8' and 	1.1 to 2.2 kohms go to measurement	Go to Step 3

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

	Check open circuit:	 'pin B10' of servo motor plug 'B'. Measurement '2b': Measure resistance between 'pin 31' of transfer box control unit plug and 'pin B8' of removed sensor plug 'B'. 	< 5 ohms	Repair wiring harness to servo motor. > End
3	Replace transfer box servo motor		> End	
4	likeniace transfer nov control module		See note on replacing control units! > End	

FAULT CODE 2038

VOLTAGE SUPPLY TO SENSORS

NOTE: This fault code relates to the voltage supply to sensors: potentiometer '1' (sensor 1), potentiometer '2' (sensor 2) and the servo motor temperature sensor, which are integrated as a unit in the servo motor.

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test

Possible causes of fault

- 'Above upper limit': voltage supply line (5 V) short circuit to B+ (12 V)
- 'Above upper limit': transfer box control unit faulty
- 'Below lower limit': voltage supply line (5 V) short circuit to ground
- 'Below lower limit': transfer box control unit faulty

Affected pins

Transfer box control unit plug:

- Pin 1 'potentiometer 1 (sensor 1) 5 V to pin B4 of 'servo motor sensor plug'
- Pin 18 'potentiometer 2 (sensor 2) 5 V to pin B10 of 'servo motor sensor plug'
- Pin 29 'voltage supply (5 V) for servo motor temperature sensor' to pin B6 of 'servo motor sensor plug'

DIAGNOSIS/TROUBLESHOOTING

NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.

2003-08 TRANSMISSION Transfer Box - 9pa Cayenne

NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control unit. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

If not OK Work instruction **Display OK** • Ignition off Measured voltage • Pull sensor plug 'B' off servo motor > 5 V approx. 5 V Check voltage supply Go to Step 2, • Ignition on Go to Step 2, 1 of potentiometer '1' measurement '2b' measurement • Measure voltage at sensor plug 'B' on and potentiometer '2': Measured voltage the wiring harness side between: 'pin '2a' < 5 VB4 and pin B3', 'pin B10 and pin B9' Go to Step 3 and 'pin B6 and ground'. Measurement '2a': • Ignition off Short circuit • Pull plug 'A' off servo motor infinity ohms between servo Measurement • Measure resistance at servo motor motor leads. plugs 'A and B' between: 'pin B10 and ^{'2b'} Go to Step 4 pin A1, A2, A3, A4', 'pin B4 and pin A1, A2, A3, A4' and 'pin B6 and pin A1, A2, A3, A4'. Measurement '2b': • Ignition off Repair wiring • Pull plug 'A' off servo motor Check short circuit to < 0.3 Vharness to servo B+: • Pull plug off transfer box control unit Measurement motor. 2c'• Ignition on --> End • Measure voltage between 'pins 1, 18, 29' of transfer box control unit plug and ground. Measurement '2c': • Ignition off Repair wiring infinity ohms harness to servo • Measure resistance at transfer box Go to Step 5 motor. control unit plug between 'pin 1 and --> End pin 15, 16, 21, 36', 'pin 18 and pin 15, 16, 21, 36' and 'pin 29 and pin 15, 16, 21, 36'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Measurement '3a':

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		 Ignition off Measure resistance between 'pins 1, 18, 29' of transfer box control unit plug and ground. 	infinity ohms Go to Step 5	Measurement '3b'
רו	Check short circuit to ground:	 Measurement '3b': On servo motor, pull off sensor plug 'B' and servo motor plug 'A' Measure resistance between 'pins 1, 18, 29' of transfer box control unit plug and ground. 	infinity ohms Go to Step 4	Repair wiring harness to servo motor. > End
4	Replace transfer box servo motor		> End	
5	5 Replace transfer box control unit		See note on repla > End	acing control units!

FAULT CODE 2039

POTENTIOMETER, TRANSFER BOX

NOTE: This fault code relates to the signal of potentiometer '2' (sensor 2) and potentiometer '1' (sensor 1) which, together with the temperature sensor, are integrated as a unit in the servo motor.

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible causes of fault

- 'Short circuit to B+': signal line of potentiometer '1/2' (sensor 1/2) short circuit to B+(12 V)
- 'Short circuit to B+': transfer box control unit faulty
- 'Open circuit/short circuit to ground': signal line of potentiometer '1/2' (sensor 1/2) open circuit or short circuit to ground
- 'Short circuit to ground': potentiometer faulty
- 'Open circuit/short circuit to ground': transfer box control unit faulty
- 'Implausible signal': potentiometer faulty

Affected pins

Transfer box control module plug:

• Pin 12 'input signal to potentiometer 1 (sensor 1)', from pin B5 of 'servo motor sensor plug'

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• Pin 31 'input signal to potentiometer 2 (sensor 2)', from pin B8 of 'servo motor sensor plug'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'short circuit to B+'

Work in	struction	Display OK	If not OK	
	Measurement '1a':			
	 Ignition off Pull plug off the transfer box control unit Ignition on Measure voltage between 'pins 12, 31' of transfer box control unit plug and ground. Measurement '1b': 	< 0.3 V go to measurement '1b'	Repair wiring harness to servo motor. > End	
¹ Check circuit		'1c'	Short circuit between servo motor leads. Go to Step 2	
	 Measure ment '1c': Measure resistance between 'pins 12, 31' and pins '1, 15, 16, 18, 21, 36' of transfer box control unit plug. 	infinity ohms	Repair wiring harness to servo motor. > End	
2 Replace	2 Replace transfer box servo motor			
	3 Replace transfer box control module		See note on replacing control units! > End	

DIAGNOSIS TROUBLESHOOTING PROCEDURE

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Troubleshooting fault type: 'Open circuit/short circuit to ground'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

V	Vork instructi	on	Display OK	If not OK
1	Check short circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pins 12 and 15, 16, 33, 44, 47 as well as between pins 31 and 2, 15, 16, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 2	go to measurement '1b'
		 Measurement '1b': Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pins 12, 31 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
2	Check open	 Measurement '2a': Pull plug 'B' off servo motor Measure resistance between 'pin B5' and 'pin B4' and 'pin B8' and 'pin B10' of servo motor plug 'B'. Measurement '2b': 	1.1 to 2.2 kohms go to measurement '2b'	Go to Step 3
		• Measure resistance between 'pins 12 and B5' of transfer box control unit plug and 'pins 31 and B8' of removed sensor plug 'B'.	< 5 ohms Go to Step 4	Repair wiring harness to servo motor. > End
3	3 Replace transfer box servo motor		> End	
Alkenlace transfer box control module		See note on rep > End	lacing control units!	

Troubleshooting for fault type: 'implausible signal'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

V	Vork instruction	Display OK	If not OK
1	Replace transfer box servo motor (potentiometer faulty)	> End	

FAULT CODE 2040

VOLTAGE SUPPLY TO TRANSFER BOX SERVO MOTOR

Diagnostic conditions

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- Ignition on
- Internal transfer box control module function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Short circuit to B+': short circuit in wiring harness (servo motor runs continuously)
- 'Short circuit to B+': control unit faulty (servo motor runs continuously)
- 'Short circuit to ground': short circuit in wiring harness (servo motor does not function)
- 'Short circuit to ground': short in servo motor winding or short circuit in servo motor leads (servo motor does not function)
- 'Short circuit to ground': control unit faulty (servo motor does not function)

Affected pins

Transfer box control module plug:

- Pin 15 'servo motor (A)', to pin A1 of 'servo motor plug A'
- Pin 16 'servo motor (B)', to pin A4 of 'servo motor plug B'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

TROUBLESHOOTING FAULT TYPE: 'SHORT CIRCUIT TO B+'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

١	Work instruction	Display OK	If not OK
	Measurement '1a':		
	Ignition off		Repair wiring

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		 Pull plug off the transfer box control unit Ignition on Measure voltage between 'pins 15, 16' of transfer box control unit plug and ground. Measurement '1b': 		harness to servo motor. > End
1	Check short circuit to B+:	 Pull plug 'A' off servo motor 	< 5 V Short circuit between servo motor leads. Go to Step 2	Go to Step 3
2	Replace transfer box servo motor> End			
3	Replace trans	fer box control module	See note on replacing control units! > End	

Troubleshooting fault type: 'short circuit to ground'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

v	Work instruction			If not OK
1	Check short circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pins 15, 16 and pins 2, 33, 36, 44, 47' of transfer box control unit plug. Measurement '1b': 	infinity ohms Go to Step 3	go to measurement '1b'
		 Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pins 15 and 16' and 'pins 15, 16 and pins 2, 33, 36, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 2	Repair wiring harness to servo motor. > End
2	Replace transfer	r box servo motor	> End	,
3	Replace transfe	r box control module	See note units! > End	on replacing control

FAULT CODE 2041

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

GROUND SUPPLY TO TRANSFER BOX SERVO MOTOR

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Short circuit to B+': short circuit in wiring harness (servo motor does not function)
- 'Short circuit to B+': control unit faulty (servo motor does not function)
- 'Short circuit to ground': short circuit in wiring harness (servo motor runs continuously)
- 'Short circuit to ground': short in servo motor winding or short circuit in servo motor leads (servo motor runs continuously)
- 'Short circuit to ground': control unit faulty (servo motor runs continuously)

Affected pins

Transfer box control module plug:

- Pin 15 'servo motor (A)', to pin A1 of 'servo motor plug A'
- Pin 16 'servo motor (B)', to pin A4 of 'servo motor plug B'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'short circuit to B+'

Work instruction	Display OK	If not OK

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		Measurement '1a':		
-	Check short	 Ignition off Pull plug off the transfer box control unit Ignition on Measure voltage between 'pins 15, 16' of transfer box control unit plug and ground. 	< 0.3 V go to measurement '1b'	Repair wiring harness to servo motor. > End
11	circuit to B+:	 Pull plug 'A' off servo motor 	< 5 V Short circuit between servo motor leads. Go to Step 2	Go to Step 3
2	2 Replace transfer box servo motor		> End	
3	Replace transfer box control module		See note on replacing control units! > End	

Troubleshooting fault type: 'short circuit to ground'

	Work instruction	n	Display OK	If not OK
1	Check short circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pins 15,16 and pins 2, 33, 36, 44, 47' of transfer box control unit plug. Measurement '1b': 	infinity ohms Go to Step 2	go to measurement '1b'
	<u>Bround</u>		infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
2	2 Replace transfer box servo motor		> End	
	Replace transfer box control module		See note o units! > End	on replacing control

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

FAULT CODE 2042

ACTIVATION OF TRANSFER BOX SERVO MOTOR

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Open circuit': open circuit between leads (servo motor does not function)
- 'Open circuit': control unit faulty (servo motor does not function)
- 'Open circuit': open circuit in servo motor winding (servo motor does not function)

Affected pins

Transfer box control unit plug:

- Pin 15 'servo motor (A)', to pin A1 of 'servo motor plug A'
- Pin 16 'servo motor (B)', to pin A4 of 'servo motor plug B'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control unit. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Wo	ork instruction	Display OK	If not OK
	Measurement '1a':		
	• Ignition off	0.8 ohms	If infinity ohms

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

	Check open circuit:	 Measure resistance (servo motor winding) between 'pins A1 and A4' of servo motor plug 'A'. Measurement Pull plug off transfer box control unit Measure resistance between 'pins 15, 16' of transfer box control unit plug and 'pins A1, A4' 	go to measurement '1b' < 5 ohms Go to Step 3	then: Go to Step 2 Repair wiring harness to servo motor. > End
2	of removed lock plug 'A'. Replace transfer box servo motor		> End	
			See note on replacing control units! > End	
S	Replace trai	nsfer box control unit		

FAULT CODE 2046

GEAR REDUCTION LED (IN CONTROL MODULE)

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

If short circuit to B+:

Engage gear reduction.

If short circuit to ground:

Do not engage gear reduction.

Possible causes of fault

'Gear reduction LED' is activated by transfer box control unit on the ground side.

- 'Short circuit to B+': gear reduction LED does not light
- 'Short circuit to ground': gear reduction LED permanently lit

Affected pins

Transfer box control module plug:

• Pin 4 'gear reduction LED', to gear reduction LED (in running gear control module) 'pin 13'

DIAGNOSIS/TROUBLESHOOTING

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

	Work instruction		Display OK	If not OK
		Measurement '1a':		
		 Switch off ignition Pull plug off transfer box control unit Pull plug off selector switch switch (running gear control module) Switch on ignition Measure voltage between 'pin 13' of selector switch plug (running gear control module) and ground. 	< 0.3 V go to measurement '1c'	go to measurement '1b'
1	Check gear reduction LED activation line for short circuit to B+:	 Measurement '1b': Switch off ignition Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 4' of transfer box control unit plug and ground. Measurement '1c': 	< 0.3 V Go to Step 6	Repair wiring. > End
		 Switch off ignition Connect plug to selector switch (running gear control module) Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 4' of transfer box control unit plug and ground. 	< 0.3 V Go to Step 2	Go to Step 5

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		 Measurement '2a': Switch off ignition Measure voltage between 'pin 4' of transfer box control unit plug and battery positive. Measurement '2b': 	< 0.3 V go to measurement '2c'	go to measurement '2b'
2	Check gear reduction LED activation line for short circuit to ground:	 Pull plug off selector switch switch (running gear control module) Measure resistance between 'pin 4' of transfer box control unit plug and ground. 	infinity ohms Go to Step 5	Repair wiring. > End
		 Pull plug off selector switch switch (running gear control module) Measure voltage between 'pin 13' of selector switch plug (running gear control module) and battery positive. 	< 0.3 V Go to Step 3	Go to Step 6
3	Check for short circuit in the wiring to selector switch (running gear control module):	 Pull plug off selector switch switch (running gear control module) Pull plug off the transfer box control unit Measure resistance between 'pin 13' of selector switch plug (running gear control module) and 'pins: 3, 4, 6, 7, 8, 11, 12, 14, 15, 16'. 	infinity ohms Go to Step 4	Repair wiring. > End
4	Check gear reduction LED activation line for open circuit:	• Measure resistance between 'pin 13' of selector switch plug (running gear control module) and 'pin 4' of transfer box control unit.	< 0.5 ohms Go to Step 6	Repair wire. > End
5	Replace selector switch (run	nning gear control module)	> End	
6	Replace transfer box control module		See note on rep units! > End	lacing control

FAULT CODE 2047

LONGITUDINAL LOCK LED (IN CONTROL MODULE)

Diagnostic conditions

• Ignition on

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• Internal transfer box control module function test

If short circuit to B+:

Engage longitudinal lock.

If short circuit to ground:

Do not engage longitudinal lock.

Possible causes of fault

'Longitudinal lock LED' is activated by transfer box control unit on the ground side.

- 'Short circuit to B+': longitudinal lock LED does not light
- 'Short circuit to ground': longitudinal lock LED permanently lit

Affected pins

Transfer box control module plug:

• Pin 20 'longitudinal lock LED', to longitudinal lock LED (in running gear control module) 'pin 14'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

V	Work instruction	-	Display OK	If not OK
		Measurement '1a':		
		 Switch off ignition Pull plug off selector switch switch (running gear control module) 	< 0.3 V	go to measurement '1b'
		• Pull plug off the transfer box control unit	go to measurement	

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

1	1	I	11.2	1
	Check longitudinal lock LED activation line for short circuit to B+:	 Switch on ignition Measure voltage between 'pin 14' of selector switch plug (running gear control module) and ground. Measurement '1b': Switch off ignition Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 20' of transfer box control unit plug and ground. Measurement '1c': 	'1c' < 0.3 V Go to Step 6	Repair wiring. > End
		 Switch off ignition Connect plug to selector switch (running gear control module) Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 20' of transfer box control unit plug and ground. 	< 0.3 V Go to Step 2	Go to Step 5
	Check longitudinal lock LED activation line for short circuit to ground:	 Measurement '2a': Switch off ignition Measure voltage between 'pin 20' of transfer box control unit plug and battery positive. Measurement '2b': Pull plug off selector switch switch (running gear control module) Measure resistance between 'pin 20' of transfer box control unit plug and ground. 	go to measurement '2c'	go to measurement '2b' Repair wiring. > End
		 Measurement '2c': Pull plug off selector switch switch (running gear control module) Measure voltage between 'pin 14' of selector switch plug (running gear 	< 0.3 V Go to Step 3	Go to Step 6

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		control module) and battery positive.		
3	Check for short circuit in the wiring to selector switch (running gear control module):	 Pull plug off selector switch switch (running gear control module) Pull plug off the transfer box control unit Measure resistance between 'pin 14' of selector switch plug (running gear control module) and 'pins: 3, 4, 6, 7, 8, 11, 12, 13, 15, 16'. 	infinity ohms Go to Step 4	Repair wiring. > End
4	Check longitudinal lock LED activation line for open circuit:	• Measure resistance between 'pin 14' of selector switch plug (running gear control module) and 'pin 20' of transfer box control unit.	< 0.5 ohms Go to Step 6	Repair wiring. > End
5	Replace selector switch (runn	ning gear control module)	> End	
6			See note on rep units! > End	lacing control

FAULT CODE 2048

TRANSVERSE LOCK LED, REAR (IN CONTROL MODULE)

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

If short circuit to B+:

Engage transverse lock.

If short circuit to ground:

Do not engage transverse lock.

Possible causes of fault

'Transverse lock LED' is activated by transfer box control unit on the ground side.

- 'Short circuit to B+': transverse lock LED does not light
- 'Short circuit to ground': transverse lock LED permanently lit

Affected pins

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Transfer box control module plug:

• Pin 35 'transverse lock LED', to transverse lock LED (in running gear control module) 'pin 6'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Work instruction		Display OK	If not OK
	 Measurement '1a': Switch off ignition Pull plug off selector switch switch (running gear control module) Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 6' of selector switch plug (running gear control module) and ground 	< 0.3 V go to measurement '1c'	go to measurement '1b'
Check transverse lock 1 LED activation line for short circuit to B+:	 control module) and ground. Measurement Switch off ignition Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 35' of transfer box control unit plug and ground. Measurement '1c': Switch off ignition 	< 0.3 V Go to Step 6	Repair wiring. > End
	• Connect plug to selector switch (running gear control module)		

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		 Pull plug off the transfer box control unit Switch on ignition Measure voltage between 'pin 35' of transfer box control unit plug and ground. 	< 0.3 V Go to Step 2	Go to Step 5
		 Measurement '2a': Switch off ignition Measure voltage between 'pin 35' of transfer box control unit plug and battery positive. Measurement '2b': 	< 0.3 V go to measurement '2c'	go to measurement '2b'
2	Check transverse lock LED activation line for short circuit to ground:	 Pull plug off selector switch switch (running gear control module) Measure resistance between 'pin 35' of transfer box control unit plug and ground. 	infinity ohms Go to Step 5	Repair wiring. > End
		 Connect plug to transfer box control unit Pull plug off selector switch switch (running gear control module) Measure voltage between 'pin 6' of selector switch plug (running gear control module) and battery positive. 	< 0.3 V Go to Step 3	Go to Step 6
3	Check for short circuit in the wiring to selector switch (running gear control module):	 Pull plug off selector switch switch (running gear control module) Pull plug off the transfer box control unit Measure resistance between 'pin 6' of selector switch plug (running gear control module) and 'pins: 3, 4, 7, 8, 11, 12, 13, 14, 15, 16'. 	Go to Step 4	Repair wiring. > End
	Check transverse lock LED activation line for open circuit:	• Measure resistance between 'pin 6' of selector switch plug (running gear control module) and 'pin 35' of transfer box control unit.	< 0.5 ohms Go to Step 6	Repair wiring. > End
	Replace selector switch (run Replace transfer box contro		> End See note on rep units!	lacing control

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

--> End

FAULT CODE 2050

TRANSFER BOX SWITCHING FAULT

NOTE: After successful read out the fault memory must be erased and after satisfying the diagnostic conditions below must be read out again!

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test
- Vehicle stationary
- Engine running
- Brake actuated
- Selector lever position 'N'
- Via the left rocker switch on the 'selector switch (running gear control module)', alternately select the functions 'off-road driving program' and 'on-road driving program' (see Driver's Manual)

Possible causes of fault

• 'Mechanical fault': mechanical wear in transfer box

Affected pins

Transfer box control unit plug:

• Pin '-'

DIAGNOSIS/TROUBLESHOOTING

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction	Display OK	If not OK
1If the fault recurs after repeatedly erasing the fault memory, then:2Repair/replace transfer box	> End	

FAULT CODE 2051

TIPTRONIC CONTROL MODULE, INCORRECT SOFTWARE VERSION

Diagnostic conditions

• Ignition on

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• Internal control module function test

Possible causes of fault

• Incorrect software version (no display)

Affected pins

Tiptronic control module plug:

- -
- -

DIAGNOSIS/TROUBLESHOOTING VG 0101

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		If not OK
1 Check software version of Tiptronic control module and correct it if necessary	> End	

FAULT CODE 2052

CONTROL UNIT SWITCHED OFF DUE TO EXCESS TEMPERATURE

NOTE: This fault may be stored after extreme oft-road driving. This does not necessarily mean a fault is present!

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock

Possible causes of fault

- 'Above upper limit': heavy demand on servo motor (mechanical stress)
- 'Above upper limit': mechanical wear of servo motor
- 'Above upper limit': transfer box control unit faulty

Affected pins

Transfer box control unit plug:

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• Pin

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control unit. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

١	Vork instruction		Display OK	If not OK
1	Check fault memory:	Check function of lock	storeu.	Go to Step 2
2	Replace servo motor:	 Erase fault memory Check function of lock Read out fault memory again 	> End	If fault is not remedied by replacing the servo motor: Go to Step 3
3	3 Replace control unit		See note on re > End	eplacing control units!

DIAGNOSIS TROUBLESHOOTING PROCEDURE

FAULT CODE 2053

TRANSFER BOX CONTROL MODULE

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

Communication problem with all control modules via CAN drive.

• No message via CAN drive (no signal/communication)

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• Internal fault in transfer box control module (faulty)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u>'.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

V	Vork instruction	Display OK	If not OK
1	CHECKING INSTRUCTIONS/CAN DATA BUS.	> End	
2	Replace transfer box control module	If CAN drive chec => End	k is OK:

FAULT CODE 2054

TRANSVERSE LOCK CONTROL MODULE

Diagnostic conditions

- Ignition on
- Internal control module function test

Possible cause of fault

- To localise the fault, read out the fault memory for the 'transverse lock control module' (Please read out fault memory)
- No message from transverse lock control module on CAN drive (no signal/communication)

Affected pins

Transfer box control module plug:

- Pin 11 'CAN drive (low)'
- Pin 42 'CAN drive (high)'

DIAGNOSIS/TROUBLESHOOTING VG 0101

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

NOTE: If there is no incoming signal/message via the CAN drive using several control modules, the CAN drive must be checked for open or short circuits. Refer to <u>'CHECKING INSTRUCTIONS/CAN DATA BUS</u> '.

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruction		Display OK	If not OK
	Read out fault memory for transverse lock control module	To eliminate further faults, please follow diagnosis/troubleshooting instructions for control module, refer to the <u>FINAL DR</u> <u>DIFFERENTIAL LOCK</u> article > End	or the transverse lock
2	<u>CHECKING</u> 2 INSTRUCTIONS/CAN DATA BUS .	> End	

FAULT CODE 2057

VOLTAGE SUPPLY TO BRAKE FOR SERVO MOTOR (A)

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Short circuit to B+': short circuit in wiring harness (brake for servo motor continuously activated)
- 'Short circuit to B+': control unit faulty (brake for servo motor continuously activated)
- 'Short circuit to ground': short circuit in wiring harness (brake for servo motor does not activate)
- 'Short circuit to ground': short in servo motor winding or short circuit in servo motor leads (brake for servo motor does not activate)
- 'Short circuit to ground': control unit faulty (brake for servo motor does not activate)

Affected pins

Transfer box control module plug:

• Pin 21 'supply voltage to brake for servo motor (A)', to pin A2 of 'servo motor plug A'

DIAGNOSIS/TROUBLESHOOTING

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'short circuit to B+'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instructi	Work instruction		If not OK
1 Check short circuit to B+:	 Measurement '1a': Ignition off Pull plug off the transfer box control unit Ignition on Measure voltage between 'pin 21' of transfer box control unit plug and ground. Measurement '1b': 	< 0.3 V go to measurement '1b'	Repair wiring harness to servo motor. > End
encuit to D+.	 Ignition off Connect plug to transfer box control unit Pull plug 'A' off servo motor Ignition on Measure voltage between 'pin A2' of servo motor plug 'A' (wiring harness side) and ground. 	< 0.5 V Short circuit between servo motor leads. Go to Step 2	Go to Step 3
2 Replace transf	fer box servo motor	> End	
Replace transfer box control module		See note on replacing control units!	

Troubleshooting fault type: 'short circuit to ground'

Work	instr	uction
11010	mou	ucuon

Display OK	If not OK	
---------------	-----------	--

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

1	Check short circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pin 21 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. Measurement '1b': 	infinity ohms Go to Step 2	go to measurement '1b'
	El ound.	 Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pin 21 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
2	2 Replace transfer box servo motor		> End	
3	3 Replace transfer box control module		See note o units! > End	on replacing control

FAULT CODE 2058

GROUND SUPPLY TO BRAKE FOR LOCK MOTOR (B)

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Short circuit to B+': short circuit in wiring harness (brake for servo motor does not activate)
- 'Short circuit to B+': short circuit in wiring harness (brake for servo motor does not activate)
- 'Short circuit to B+': control unit faulty (brake for servo motor does not activate)

Affected pins

Transfer box control unit plug:

• Pin 36 'ground supply to brake for servo motor (B)', to pin A3 of 'servo motor plug A'

DIAGNOSIS/TROUBLESHOOTING

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control unit. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'short circuit to B+'

DIAGNOSIS TROUBLESHOOTING PROCEDURE

Work instruct	ion	Display OK	If not OK
	 Measurement '1a': Ignition off Pull plug off transfer box control unit Ignition on Measure voltage between 'pin 36' of transfer box control unit plug and ground. 	< 0.3 V go to measurement '1b'	Repair wiring harness to servo motor. > End
1 Check short circuit to B+:	 Measurement Ignition off Connect plug to transfer box control unit Pull plug 'A' off servo motor Ignition on Measure voltage between 'pin A3' of servo motor plug 'A' (wiring harness side) and ground. 	< 0.3 V Short circuit between servo motor leads. Go to Step 2	Go to Step 3
2 Replace trans	fer box servo motor	> End	
Replace transfer box control unit		See note on replacing control units! > End	

FAULT CODE 2059

SERVO MOTOR TEMPERATURE SENSOR

NOTE: The servo motor temperature sensor is integrated with potentiometer '1' (sensor

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

1) and potentiometer '2' (sensor 2) as a unit in the servo motor.

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible causes of fault

- 'Open circuit/short circuit to B+': short circuit to B+ (12 V) in the voltage supply (5 V)/ground supply wiring
- 'Open circuit/short circuit to B+': open circuit in the voltage supply (5 V)/ground supply wiring
- 'Short circuit to ground': short circuit to ground in the voltage supply (5 V)/ground supply wiring
- 'Above upper limit': short circuit to B+ (12 V) in the voltage supply (5 V) wiring
- 'Above upper limit', servo motor temperature sensor faulty

Affected pins

Transfer box control module plug:

- Pin 29 'voltage supply (5 V) for servo motor temperature sensor' to pin B6 of 'servo motor sensor plug'
- Pin 44 'ground for servo motor temperature sensor' to pin B7 of 'servo motor sensor plug'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'Open circuit/short circuit to B+' and 'above upper limit'

[Work instruction		Display OK	If not OK
	Check voltage/ground	 Ignition off Pull sensor plug 'B' off servo motor 	Approx, 5 V	Measured voltage > 5 V Go to Step 2,

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

	supply of servo motor temperature sensor:	 Ignition on Measure voltage between 'pins B6 and B7' of sensor plug 'B' (wiring harness side). 	measurement '2a'	measurement '2b' Measured voltage < 5 V Go to Step 3
		 Measurement '2a': Ignition off Pull plug 'A' off servo motor Measure resistance on servo motor between: 'pins B6, B7 and pins A1, A2, A3, A4'. Measurement '2b': 	infinity ohms Go to Step 3	Short circuit between servo motor leads. Go to Step 4
• /	Check short circuit to B+/above upper limit:	 Ignition off Pull plug 'A' off servo motor Pull plug off the transfer box control unit Ignition on Measure voltage between 'pins 29, 44' of transfer box control unit plug and ground. 	< 0.3 V Measurement '2c'	Repair wiring harness to servo motor. > End
		 Measurement '2c': Ignition off Measure resistance between 'pins 29, 44 and pins 15, 16, 21' of transfer box control unit plug. 	infinity ohms Go to Step 5	Repair wiring harness to servo motor. > End
3	Check open circuit:	 Measurement '3a': Measure resistance between 'pin B6' and 'pin B7' of servo motor plug 'B'. Measurement '3b': 	1.1 kohms at 21° C go to measurement '3b'	Go to Step 4
	-	• Measure resistance between 'pins 29, 44' of transfer box control unit plug and 'pins B6, B7' of removed sensor plug 'B'.	Go to Step 5	Repair wiring harness to servo motor. > End
	Replace transfer box serve	> End See note on repla	cing control units!	
5	5 Replace transfer box control module See note on replacing control units > End			ening control units:

Troubleshooting fault type: 'short circuit to ground'

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

DIAGNOSIS TROUBLESHOOTING PROCEDURE

V	Work instruction		Display OK	If not OK
1	Check short circuit to ground:	 Measurement '1a': Ignition off Pull plug off transfer box control unit Measure resistance between 'pin 29' of transfer box control unit plug and ground. 	Go to Step 3	Measurement '1b'
		 On servo motor, pull off sensor plug 'B' and servo motor plug 'A' Measure resistance between 'pin 29' of transfer box control unit plug and ground. 	infinity ohms Go to Step 2	Repair wiring harness to servo motor. > End
2	Replace transfer b	ox servo motor	> End	
	Replace transfer box control module		See note o > End	on replacing control units!

FAULT CODE 2060

VOLTAGE SUPPLY FOR SERVO MOTOR TEMPERATURE SENSOR

NOTE: The servo motor temperature sensor is integrated with potentiometer '1' (sensor 1) and potentiometer '2' (sensor 2) as a unit in the servo motor.

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test

Possible causes of fault

- 'Short circuit to B+': voltage supply line (5 V) short circuit to B+ (12 V)
- 'Short circuit to B+': transfer box control unit faulty
- 'Short circuit to ground': voltage supply line (5 V) short circuit to ground
- 'Short circuit to ground': transfer box control unit faulty

Affected pins

Transfer box control module plug:

• Pin 29 'voltage supply (5 V) for servo motor temperature sensor' to pin B6 of 'servo motor sensor plug'

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Work instruction		Display OK	If not OK
Check voltage supply 1 for servo motor temperature sensor:	 Ignition off Pull sensor plug 'B' off servo motor Ignition on Measure voltage between 'pin B6 and ground' of sensor plug 'B' (wiring harness side). 	Approx. 5 V Go to Step 2, measurement '2a'	Measured voltage > 5 V Go to Step 2, measurement '2b' Measured voltage < 5 V Go to Step 3
	 Measurement '2a': Ignition off Pull plug 'A' off servo motor Measure resistance on servo motor between: 'pins B6 and pins A1, A2, A3, A4'. Measurement '2b': 	infinity ohms Measurement '2b'	Short circuit between servo motor leads. Go to Step 4
2 Check short circuit to B+:	 Ignition off Pull plug 'A' off servo motor Pull plug off the transfer box control unit Ignition on Measure voltage between 'pin 29' of transfer box control unit plug and ground. 	< 0.3 V Measurement '2c'	Repair wiring harness to servo motor. > End
	Measurement '2c':		
	Ignition off	infinity ohms	Repair wiring harness to servo

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		• Measure resistance between 'pin 29 and pins 15,16, 21, 36' of transfer box control unit plug.	Go to Step 5	motor. > End
2	Check short circuit to	 Measurement '3a': Ignition off Measure resistance between 'pin 29' of transfer box control unit plug and ground. Measurement '3b': 	infinity ohms Go to Step 5	Measurement '3b'
3	ground:		infinity ohms Go to Step 4	Repair wiring harness to servo motor. > End
4	Replace transfer box serv	vo motor	> End	
5	Replace transfer box con	trol module	See note on replac > End	ing control units!

FAULT CODE 2373

CURRENT SENSOR IN CONTROL UNIT

NOTE: The current sensor is integrated in the transfer box control unit and can not be separately replaced.

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test

Possible causes of fault

• 'implausible signal'

Affected pins

Transfer box control unit plug:

• Pin

DIAGNOSIS/TROUBLESHOOTING

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control unit. After the test drive, read out the fault memory again with the Porsche System Tester II No. 9588. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

DIAGNOSIS	TROUBLESHOOTI	NG PROCEDURE

V	Work instruction	on	Display OK	If not OK
1	Check fault memory:	• Check function	•	If, additionally, fault codes 2057 or 2058 stored, then diagnose/troubleshoot these codes. > End
2	2 Replace control unit		See note on rep > End	lacing control units!

FAULT CODE 2409

SERVO MOTOR BRAKE

Diagnostic conditions

- Ignition on
- Internal transfer box control module function test
- Engine running
- Selector lever position 'P'
- Engage longitudinal lock/gear reduction

Possible causes of fault

- 'Open circuit/short circuit to ground': open circuit/short circuit in wiring harness (brake for servo motor does not activate)
- 'Open circuit/short circuit to ground': short in servo motor winding (brake) or open circuit/short circuit in servo motor leads (brake for servo motor does not activate)
- 'Open circuit/short circuit to ground': control unit faulty (brake for servo motor does not activate)

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

Affected pins

Transfer box control module plug:

- Pin 21 'supply voltage to brake for servo motor (A)', to pin A2 of 'servo motor plug A'
- Pin 36 'ground supply to brake for servo motor (B)', to pin A3 of 'servo motor plug A'

DIAGNOSIS/TROUBLESHOOTING

- NOTE: Visual inspection: In the next troubleshooting section, please check first that the affected 'pins' of the transfer box control unit plug connection and the 'pins' of the plug connections on the servo motor are neither damaged nor corroded. Remove any soiling or corrosion/oxidation. Replace damaged parts/wires.
- NOTE: Control unit replacement: Before replacing the 'transfer box control unit', the ground connections, power supply and plug connections on the control unit must be checked as OK. Please observe the coding of the control module. After the test drive, read out the fault memory with the 9588 Porsche System Tester II again. Additional causes of faults that could damage the 'transfer box control unit' should be detected and remedied.

Troubleshooting fault type: 'electrical fault in electric circuit'

Work instruction		Display OK	If not OK
	Measurement '1a': • Ignition off	< 0.3 V	Repair wiring
	Pull plug off the transfer box control unitIgnition on	go to measurement '1b'	harness to servo motor. > End
Check short circuit	 Measure voltage between 'pins 21, 36' of transfer box control unit plug and ground. Measurement '1b': 		
to B+:	 Ignition off Connect plug to transfer box control unit Pull plug 'A' off servo motor Ignition on Gear reduction/longitudinal lock not 	< 0.3 V Go to Step 2	Go to Step 5
	 engaged Measure voltage between 'pins A2, A3' of servo motor plug 'A' (wiring harness side) and ground. 		

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		Measurement '2a':		
	Check short circuit to ground:	 Ignition off Pull plug off transfer box control unit Ignition off Measure voltage between 'pin A2' of transfer box servo motor plug 'A' (wiring harness side) and battery positive. 	< 0.3 V go to measurement '2c'	go to measurement '2b'
2		 Pull plug off transfer box control unit Measure resistance between 'pin 21 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. Measurement '2c': 		Repair wiring harness to servo motor. > End
		 Measure resistance between 'pin A2 and ground' of servo motor plug 'A'. 	Go to Step 3	Go to Step 4
	Check open	 Measurement '3a': Measure resistance between 'pins A2 and A3' of servo motor plug 'A'. 	Approx. 20 ohms go to measurement '3b'	Go to Step 4
3	circuit/winding short circuit:	 Measurement '3b': Pull plug off the transfer box control unit Measure resistance between 'pins 21, 36' of transfer box control unit plug and 'pins A2, A3' of servo motor plug 'A' (wiring harness side). 	< 5 ohms Go to Step 5	Repair wiring harness to servo motor. > End
4	Replace transfer box	x servo motor	> End	
5	Replace transfer box control module		See note on rep units! > End	lacing control

Troubleshooting fault type: 'Open circuit/short circuit to ground'

Work instruction		Display OK	If not OK
	Measurement '1a':		
Check short 1 circuit to ground:	 Ignition off Pull plug off transfer box control unit	infinity ohms Go to Step 2	go to measurement '1b'
	• Measure resistance between 'pins 21, 36 and		

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

		pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug.		
		 Measurement '1b': Pull plugs 'A' and 'B' off servo motor Measure resistance between 'pins 21, 36 and pins 2, 15, 16, 33, 44, 47' of transfer box control unit plug. 	infinity ohms Go to Step 3	Repair wiring harness to servo motor. > End
2	Check open circuit:	 Measurement '2a': Pull plug 'A' off servo motor Measure resistance between 'pin A2' and 'pin A3' of servo motor plug 'A'. 	Approx. 20 ohms go to measurement '2b'	Go to Step 3
		 Measurement '2b': Measure resistance between 'pins 21, 36' of transfer box control unit plug and 'pins A2, A3' of removed servo motor plug 'A' (wiring harness side). 	< 5 ohms Go to Step 4	Repair wiring harness to servo motor. > End
3	Replace trans	fer box servo motor	> End	·
4	Replace trans	fer box control module	See note on rep > End	lacing control units!

FAULT CODE 2411

LONGITUDINAL LOCK

NOTE: After successful read out the fault memory must be erased and after satisfying the diagnostic conditions below must be read out again!

Diagnostic conditions

- Ignition on
- Internal transfer box control unit function test
- Vehicle stationary
- Engine running
- Brake actuated
- Selector lever position 'N'
- Via the left rocker switch on the 'selector switch (running gear control module)', alternately select the functions LOW RANGE and longitudinal lock LOW RANGE 100% (see Driver's Manual)

Possible causes of fault

2003-08 TRANSMISSION Transfer Box - 9pa_Cayenne

• 'Mechanical fault': mechanical wear in transfer box

Affected pins

Transfer box control unit plug:

• Pin '-'

DIAGNOSIS/TROUBLESHOOTING

Work instruction	Display OK	If not OK
1If the fault recurs after repeatedly erasing the fault memory, then:Repair/replace transfer box	> End	